

Page 1 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA		
	GENERAL INFORMATION	
Date and Time of Inspection:	Date Report Written:	
Tue, 02/25/2020 11:51 AM	2/25/2020 3:55:45 PM	
Inspection Type:		

Weekly

SITE INFORMATION				
Construction Site Name:				
2188 Cobble Hill, San Mateo, CA				
Construction stage and completed activities:	Approximate area of site that is exposed:			
Grading	100.00			
General Photo: 🛛 Yes 🗌 No	Action Photo: Yes No			
WEA	THER			
Estimate storm beginning:	Estimate storm duration:			
Estimate time since last storm:	Rain gauge reading and location:			
	0.00			
:Is a "Qualifying Event" predicted or did one occur (i.e., 0.5"	rain with 48-hrs or greater between events)?			
No				
Exemption Documentation (explanation required if inspection could not be conducted). Visual inspections are not required outside of business hours or during dangerous weather conditions such as flooding or electrical storms.				

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

CERTIFICATION STATEMENT AND SIGNATURES:

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

Neil Trenerry			Tue, 02/25/2020
Inspector's Name – Printed	Inspector's Signature	Inspector's Title	Date

Add Category

1	1 Good Housekeeping for Construction Material					🗙 Yes 🗌 No 🛛 X
Add Location		In Complaince	Action Required	Findings and Remedial action documentation		
Loc	ation 1:	Job site				X



Page 2 of 9

High	ect Name and Loca nlands 8 Cobble Hill, San								
1.1	Inventory of produced designed to be out	ucts (excluding materials utdoors)	N/A					+	X
1.2	Stockpiled constr use are covered a	uction materials not actively in and bermed	N/A		Ī			+	X
1.3		stored in watertight containers secondary containment, or in a sed storage shed	N/A					+	X
1.4	Construction mat	erials are minimally exposed to	N/A					+	X
1.5		the off-site tracking of materials and properly effective	Yes					+	X
Ger	neral comments		1 '		•				
2	Good Houseke	eeping for Waste Manageme	ent				Yes 🗌 No	c	X
	Add	Location	In Complaince	Acti Requ	-	Findings and Remedial action	on documentation	1	
Loc	ation 1:	Job site							Х
2.1		and materials are prevented sed into the storm drain system	N/A					+	x
2.2		re contained to prevent	N/A					+	X
2.3	Sanitation facilitie	es are clean and with no s and spills	N/A		Ì			+	x
2.4	Equipment is in p	lace to cover waste disposal end of business day and during	N/A					+	X
	rain events	, , , , , , , , , , , , , , , , , , ,			· · · · · ·			_	
2.5	prevented from d system / receiving	waste disposal containers are ischarging to the storm drain a water	N/A					+	X
2.6	Stockpiled waste	material is securely protected in if not actively in use	N/A					+	X
2.7	Procedures are in and nonhazardou	n place for addressing hazardous is spills	Yes					+	X
2.8	Appropriate spill assigned and trai	response personnel are ned	Yes					+	X
2.9	Equipment and m available onsite	naterials for cleanup of spills is	Yes					+	X
2.10	Washout areas (appropriately to p into the underlyin	e.g., concrete) are contained prevent discharge or infiltration g soil	N/A					+	X
Ger	neral comments								
3	Good Houseke	eeping for Vehicle Storage a	and Maintena	nce			Yes 🗌 No	S	Х
	Add	Location	In Complaince	Acti Requ		Findings and Remedial action	on documentation	1	
Loc	ation 1:	Job site							X
3.1	fuel from leaking surface waters	place to prevent oil, grease, or into the ground, storm drains, or	Yes					+	X
3.2		vehicles are fueled, maintained, esignated area with appropriate	N/A					+	X
3.3		oment leaks are cleaned disposed of properly	Yes					+	X
Ger	neral comments								



Page <u>3</u> of <u>9</u>

Hig	ect Name and Loc hlands 8 Cobble Hill, San					
4	Good Housek	eeping for Landscape Mater	ials			XYes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
4.1		cape materials such as mulches ontained and covered when not	N/A			+ X
4.2		pe material has not been applied orecasted rain event or during an	N/A			+ X
4.3		pe materials are applied at tes in accordance with commendations	N/A			+ X
4.4	Bagged erodible on pallets and co	landscape materials are stored vered	N/A			+ X
Ger	neral comments		1			
5	Good Housek	eeping for Air Deposition of	Site Materials	S		🗙 Yes 🗌 No 🛛
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
5.1	onsite to control t	ing measures are implemented the air deposition of site m site operations	Yes			+ X
Ger	neral comments					
6	Non-Stormwat	ter Management	[]			Yes 🗌 No 🗙
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
6.1	Non-Stormwater controlled	discharges are properly	Yes			+ ×
6.2	stormwater disch drainage systems		N/A			+ X
6.3	unauthorized nor	ed in a manner to prevent nstormwater discharges to r drainage systems.	N/A			+ X
Gei	neral comments					
7	Erosion Contr	ols				🛛 Yes 🗌 No 🛛
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
7.1		ntrols are effectively implemented	Yes			+ X
7.2	inactive (ie, not s	er is provided for disturbed areas cheduled to be disturbed for 14 finished slopes, open space, d completed lots	Yes			+ X
7.3	The use of plastic	c materials is limited in cases inable, environmentally friendly	Yes			+ X



Page <u>4</u> of <u>9</u>

9

Project Name Highlands 2188 Cobble						
General com	ments					
8 Sedime	ent Cont	rols				Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Location 1:		Job site				X
	olling erosi	are established and effective on and sediment discharges	Yes			+ X
		ts are stabilized to control ent discharges from the site	Yes			+ X
8.3 Sedimer	nt basins a	are properly maintained	N/A			+ X
slope an	at grade	ontrol along toe of slope, face of breaks (Risk Level 2 & 3 Only)	N/A			+ X
entrance	es and exit	activity to and from site to ts that employ effective controls racking (Risk Level 2 & 3 Only)	Yes		+ >	
controls, controls and prote	at entrance	drain inlets and perimeter ntrol BMPs and pollutants es and exits are maintained n activities the reduce their k Level 2 & 3 Only)	Yes			+ X
8.7 Inspect a Level 2 &		ate access roads daily (Risk	Yes			+ X
General com	ments					
9 Run-Or	n and Ru	In-Off Controls				Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Location 1:		Job site				x
		is effectively managed and n all disturbed areas.	Yes			+ X
General com	ments					
III. CORRE	ECTIVE	ACTION AND SWPPP M	ODIFICATIO	NS DESCRI	PTIONS:	Add Category

explanation of the general location and the rationale for the additional or different BMPs	
Additional space to describe inspection findings and corrective actions if needed. Provide brief	
III. CORRECTIVE ACTION AND SWPPP MODIFICATIONS DESCRIPTIONS:	A

1

Yes No

Х



Page 5 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category

Location



Comments:

Location



Page 6 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category

Location



Comments:

Category

Location



Page 7 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS Category Location Comments: Category Location



Page 8 of 9

Project Name and Location
Highlands
2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS





Category

Location



Page 9 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA						
ACTION ITEM PHOTOS						
Category						
Location						

Before Photo

Comments:

After Photo

Comments: