

Page 1 of 8

I FORMATION
Date Report Written:
3/19/2020 6:20:26 PM

SITE INFORMATION			
Construction Site Name:			
2188 Cobble Hill, San Mateo, CA			
Construction stage and completed activities:	Approximate area of site that is exposed:		
Grading	100.00		
General Photo: 🛛 Yes 🗌 No	Action Photo: Yes No		
WEA	THER		
Estimate storm beginning:	Estimate storm duration:		
Estimate time since last storm:	Rain gauge reading and location:		
	0.03		
:Is a "Qualifying Event" predicted or did one occur (i.e., 0.5" i	rain with 48-hrs or greater between events)?		
No			
Exemption Documentation (explanation required if insper required outside of business hours or during dangerous wea			

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

CERTIFICATION STATEMENT AND SIGNATURES:

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

Neil Trenerry	N		Thu, 03/19/2020
Inspector's Name – Printed	Inspector's Signature	Inspector's Title	Date

Add Category

1 Good Housekeeping for Construction Material					🗙 Yes 🗌 No 🛛 X
Adc	In Complaince	Action Required	Findings and Remedial actior	n documentation	
Location 1:	Job site				X



Page 2 of 8

Hig	ect Name and Location nlands 8 Cobble Hill, San Mate							
1.1	Inventory of products designed to be outdoo		N/A				+	X
1.2	Stockpiled constructio use are covered and b	on materials not actively in permed	N/A				+	X
1.3		ed in watertight containers ndary containment, or in a storage shed	N/A				+	x
1.4	precipitation	s are minimally exposed to	N/A				+	X
1.5	BMPs preventing the or are implemented and	off-site tracking of materials properly effective	Yes				+	Х
Ger	neral comments							
2	Good Housekeepi	ng for Waste Manageme	ent			Yes 🗌 No	,	X
	Add Loca		In	Action				
		ation	Complaince	Required	Findings and Remedial action	n documentation		
Loc	ation 1: Job	site						Х
2.1		materials are prevented nto the storm drain system	N/A					x
2.2	Portable toilets are co discharges of waste	-	Yes					X
2.3	Sanitation facilities are apparent for leaks and		Yes				-	x
2.4	Equipment is in place	to cover waste disposal of business day and during	N/A					X
2.5	Discharges from wast	e disposal containers are arging to the storm drain ter	N/A				+	X
2.6		erial is securely protected	N/A				+	X
2.7	Procedures are in place and nonhazardous spi	ce for addressing hazardous ills	Yes				+	X
2.8	Appropriate spill responses assigned and trained	onse personnel are	Yes				+	X
2.9	available onsite	ials for cleanup of spills is	Yes				+	X
2.10		concrete) are contained nt discharge or infiltration il	N/A				+	X
Ger	neral comments							
3	Good Housekeepi	ng for Vehicle Storage a	and Maintenar	nce		Yes 🗌 No)	X
	Add Location In Action Complaince Required Findings and Remedial action documen		n documentation					
Loc	ation 1: Job	o site						Х
3.1		e to prevent oil, grease, or the ground, storm drains, or	Yes					X
3.2		cles are fueled, maintained, nated area with appropriate	N/A				+	x
3.3				+	X			
Ger	neral comments							



Page <u>3</u> of <u>8</u>

High	ect Name and Loc hlands 8 Cobble Hill, San					
4	Good Housek	eeping for Landscape Mater	ials			Yes No X
	Adc	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				×
4.1	and topsoil are control actively in use	cape materials such as mulches ontained and covered when not	N/A			+ >
4.2		pe material has not been applied orecasted rain event or during an	N/A			+ >
4.3		pe materials are applied at tes in accordance with commendations	N/A			+ >
4.4	Bagged erodible on pallets and co	landscape materials are stored	N/A			+ >
Ger	neral comments		<u>. </u>			
5	Good Housek	eeping for Air Deposition of	Site Materials	6		Yes No 🗴
	Adc	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				×
5.1	onsite to control	ing measures are implemented the air deposition of site m site operations	Yes			+ >
Ger	neral comments					
6	Non-Stormwat	ter Management				Yes 🗌 No 🗡
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				×
6.1	Non-Stormwater controlled	discharges are properly	Yes			+ >
6.2	stormwater disch drainage system	arges to surface waters or s	N/A			+ >
6.3	unauthorized nor	ed in a manner to prevent nstormwater discharges to drainage systems.	Yes			+ >
Ger	neral comments					
7	Erosion Contr	ols			r	Yes 🗌 No 🗴
	Adc	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				×
7.1		ntrols are effectively implemented	Yes			+ >
7.2	inactive (ie, not s days) as well as utility backfill, and		Yes			+
7.3		c materials is limited in cases inable, environmentally friendly s	Yes			+ >



Page <u>4</u> of <u>8</u>

Hig	ect Name and Loca hlands 8 Cobble Hill, San						
Gei	neral comments						
8	Sediment Cont	trols			Xes	No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial action docume	ntation	
Loc	cation 1:	Job site					X
8.1		s are established and effective sion and sediment discharges	Yes				+ X
8.2		its are stabilized to control nent discharges from the site	Yes			-	+ X
8.3	Sediment basins	are properly maintained	N/A				+ X
8.4		control along toe of slope, face of breaks (Risk Level 2 & 3 Only)	N/A				+ X
8.5	entrances and ex	activity to and from site to its that employ effective controls tracking (Risk Level 2 & 3 Only)	Yes				+ X
8.6	controls, runoff co controls at entran and protected from effectiveness (Ris	drain inlets and perimeter ontrol BMPs and pollutants ces and exits are maintained m activities the reduce their sk Level 2 & 3 Only)	Yes				+ X
8.7	Inspect all immed Level 2 & 3 Only)	liate access roads daily (Risk	Yes			-	+ ×
Gei	neral comments						
9	Run-On and R	un-Off Controls			Yes	No	X
	Add Location In Action Complaince Required Findings and Remedial action documentation			ntation			
Loc	cation 1:	Job site					X
9.1		e is effectively managed and m all disturbed areas.	Yes			-	+ X
Gei	neral comments						
						d Catogo	2014

1	Yes No X
Additional space to describe inspection findings and corrective actions if needed. Provide brief explanation of the general location and the rationale for the additional or different BMPs	
III. CORRECTIVE ACTION AND SWPPP MODIFICATIONS DESCRIPTIONS:	Add Category



Page 5 of 8

Project Name and Location
Highlands
2188 Cobble Hill, San Mateo, CA

Category Location

Comments:

Category

Location



Page 6 of 8

Project Name and Location Highlands
2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category	
Location	



Comments:

Category

Location



Page 7 of 8

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	`	
	GENERAL	PHOTOS
Category		
Location		
Comments:	Dirt against silt fence needs removing befo	ore next rain.
Category		
Location		



Page <u>8</u> of <u>8</u>

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
ACTION ITEM PHOTOS			
Category			
Location			

Before Photo

Comments:

After Photo

Comments: