

Page 1 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA				
GENERAL INFORMATION				
Date and Time of Inspection:	Date Report Written:			
Wed, 07/22/2020 09:32 AM	7/22/2020 1:56:48 PM			

## Inspection Type:

Weekly

SITE INFORMATION			
Construction Site Name:			
2188 Cobble Hill, San Mateo, CA			
Construction stage and completed activities:	Approximate area of site that is exposed:		
Grading/foundations.	100.00		
General Photo: 🛛 Yes 🗌 No	Action Photo: Yes No		
WEA	THER		
Estimate storm beginning:	Estimate storm duration:		
Estimate time since last storm:	Rain gauge reading and location:		
	0.00		
:Is a "Qualifying Event" predicted or did one occur (i.e., 0.5"	rain with 48-hrs or greater between events)?		
No			
Exemption Documentation (explanation required if insp required outside of business hours or during dangerous wea	ection could not be conducted). Visual inspections are not ather conditions such as flooding or electrical storms.		
Foundation			

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"* 

## **CERTIFICATION STATEMENT AND SIGNATURES:**

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"* 

Neil Trenerry	N		Wed, 07/22/2020
Inspector's Name – Printed	Inspector's Signature	Inspector's Title	Date

Add Category

1 Good Houseke	🗙 Yes 🗌 No 🛛 X				
Add Location		In Complaince	Action Required	Findings and Remedial action	documentation
Location 1:	Job site				X



Page 2 of 9

_						
High	roject Name and Location Highlands					
218	8 Cobble Hill, San	Mateo, CA				
1.1	Inventory of prod designed to be or	Yes			+ X	
1.2	Stockpiled constr	ruction materials not actively in	N/A			+ X
	use are covered a	and bermed stored in watertight containers				
1.3		secondary containment, or in a	Yes			+ X
1.4		erials are minimally exposed to	Yes			+ X
1.5		the off-site tracking of materials and properly effective	Yes			+ X
Ger	neral comments	Some trash cleanup needed				
2	Good Houseke	eeping for Waste Manageme	ent			XYes No X
	Add	Location	In	Action		
	, rud		Complaince	Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site			•	x
2.1		r and materials are prevented sed into the storm drain system	Yes			+ X
2.2		re contained to prevent	Yes			+ X
2.3	Sanitation facilitie apparent for leak	es are clean and with no s and spills	Yes			+ X
2.4		lace to cover waste disposal	N/A			+ X
	rain events	end of business day and during			1	
2.5		waste disposal containers are ischarging to the storm drain	N/A			+ X
	system / receiving	-			- -	
2.6		material is securely protected in if not actively in use	N/A			+ X
2.7	Procedures are in and nonhazardou	n place for addressing hazardous us spills	Yes			+ X
2.8	Appropriate spill assigned and trai	response personnel are ned	Yes			+ X
2.9	available onsite	naterials for cleanup of spills is	Yes			+ X
2.10	) Washout areas (e appropriately to p	e.g., concrete) are contained prevent discharge or infiltration	N/A			+ X
	into the underlyin	g soil				
Ger	neral comments					
3	Good Houseke	eeping for Vehicle Storage a	and Maintena	nce		Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
3.1	fuel from leaking	place to prevent oil, grease, or into the ground, storm drains, or	Yes			+ X
3.2	surface waters All equipment or	vehicles are fueled, maintained,				
3.2		esignated area with appropriate	N/A			+ X
3.3		pment leaks are cleaned disposed of properly	Yes			+ X
Ger	neral comments					



Page <u>3</u> of <u>9</u>

Hig	ect Name and Loc hlands 8 Cobble Hill, San					
4	Good Housek	eeping for Landscape Mater	ials			🗙 Yes 🗌 No 🛛
	Adc	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
4.1 Stockpiled landscape materials such as mulches and topsoil are contained and covered when not actively in use		N/A			+ X	
4.2		pe material has not been applied orecasted rain event or during an	N/A			+ X
4.3		pe materials are applied at tes in accordance with commendations	N/A			+ X
4.4	Bagged erodible on pallets and co	landscape materials are stored vered	N/A			+ X
Ger	neral comments		1			
5	Good Housek	eeping for Air Deposition of	Site Materials	S		🗙 Yes 🗌 No 🛛
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
5.1	onsite to control	ing measures are implemented the air deposition of site m site operations	Yes			+ X
Ger	neral comments					
6	Non-Stormwat	ter Management	[]			Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
6.1	Non-Stormwater controlled	discharges are properly	Yes			+ ×
6.2	stormwater disch drainage systems		N/A			+ X
6.3	unauthorized nor	ed in a manner to prevent nstormwater discharges to r drainage systems.	Yes			+ X
Gei	neral comments					
7	Erosion Contr	ols				🛛 Yes 🗌 No 🛛
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	cation 1:	Job site				×
7.1		ntrols are effectively implemented	Yes			+ X
7.2	inactive (ie, not s	er is provided for disturbed areas cheduled to be disturbed for 14 finished slopes, open space, d completed lots	Yes			+ X
<ul> <li>The use of plastic materials is limited in cases when more sustainable, environmentally friendly alternatives exists</li> </ul>		Yes			+ X	



Page <u>4</u> of <u>9</u>

9

Project Name Highlands 2188 Cobble						
General com	ments					
8 Sedime	ent Cont	rols				Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Location 1:		Job site				X
	olling erosi	are established and effective on and sediment discharges	Yes			+ X
		ts are stabilized to control ent discharges from the site	Yes			+ X
8.3 Sedimen	nt basins a	are properly maintained	N/A			+ X
slope an	8.4 Linear sediment control along toe of slope, face of slope an at grade breaks (Risk Level 2 & 3 Only)		N/A			+ X
8.5 Limit construction activity to and from site to entrances and exits that employ effective controls to prevent offsite tracking (Risk Level 2 & 3 Only)		Yes			+ X	
controls, controls and prote	at entrance	drain inlets and perimeter ntrol BMPs and pollutants es and exits are maintained n activities the reduce their k Level 2 & 3 Only)	Yes			+ X
8.7 Inspect a Level 2 &		ate access roads daily (Risk	Yes			+ X
General com	ments					
9 Run-Or	n and Ru	In-Off Controls				Yes No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Location 1:		Job site				x
		is effectively managed and n all disturbed areas.	Yes			+ X
General com	ments					
III. CORRE	ECTIVE	ACTION AND SWPPP M	ODIFICATIO	NS DESCRI	PTIONS:	Add Category

explanation of the general location and the rationale for the additional or different BMPs	
Additional space to describe inspection findings and corrective actions if needed. Provide brief	
III. CORRECTIVE ACTION AND SWPPP MODIFICATIONS DESCRIPTIONS:	A

1

Yes No

Х



Page <u>5</u> of <u>9</u>

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	
	GENERAL PHOTOS
Category	
Location	
Comments:	
Category	
Location	



Page <u>6</u> of <u>9</u>

	circui	
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA		
	GENERAL	PHOTOS
Category		
Location		

Comments: Lot 10

Category

Location



Page 7 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

	GENERAL	. PHOTOS	
Category			]
Location			]
			1
Comments:	Lot 9-10		
Category			]
Location			]



Page 8 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

## **GENERAL PHOTOS**

Catego	ry
--------	----

Location



Location



Page 9 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
ACTION ITEM PHOTOS			
Category			
Location			

Before Photo

Comments:

After Photo

Comments: