

							Page		of	10
Project Name and Loca Highlands 2188 Cobble Hill, San										
			GENERA	L INFORMA	ATION					
Date and Time of	Inspection:			Date Re	eport Written:					
Wed, 08/12/2020 0	9:27 AM			8/12/20	20 3:06:26 PM					
Inspection Type:										
Weekly										
			SITE II	NFORMATI	ON					
Construction Site	Name:									
2188 Cobble Hill, Sa	an Mateo, CA	1								
Construction stage	and compl	eted activities	<u> </u>	Approxi	imate area of s	site that is	exposed	:		
Vertical				80.00						
General Photo: 🔀	Yes No	ı		Action F	Photo: Yes	s No				
			W	'EATHER						
Estimate storm beginning:			Estimat	e storm duration	on:					
Estimate time sinc	e last storm	:		Rain ga	uge reading a	nd locatio	n:			
				0.00						
:Is a "Qualifying E No Exemption Docu required outside o	mentation (explanation r	equired if in	spection c	ould not be co	onducted	l). Visual i	nspecti		are no
•	tify that this	report is true,	accurate, an		he person who					۱.
Inspector – Certific "I certify that this r			•	•			•	ition.		
Neil Trenerry N						Wed	d, 08/12	2/202	20	
Inspector's Name - Printed Inspector's Signatu		gnature	Inspect	or's Title		Date				
									Ado	d Catego
1 Good Houseke	eping for Co	onstruction Ma	terial					∑ Ye	es [No
Add	Location		In Complaince	Action Required	Findings a	and Reme	dial action	docun	nent	ation
Location 1:	Job site									



10

2 of

Page



High	ect Name and Loca nlands 8 Cobble Hill, San					
1.1	Inventory of produ designed to be ou	ucts (excluding materials	Yes			+ X
1.2		uction materials not actively in	N/A			+ X
1.3		stored in watertight containers secondary containment, or in a sed storage shed	Yes			+ X
1.4	Construction mate precipitation	erials are minimally exposed to	Yes			+ X
1.5		the off-site tracking of materials and properly effective	Yes			+ X
Ger	neral comments					
2	Good Houseke	eeping for Waste Manageme	ent			☐ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
2.1		and materials are prevented sed into the storm drain system	Yes			+ X
2.2	Portable toilets ar discharges of was	re contained to prevent ste	Yes			+ X
2.3	Constantion facilities are along and with me		Yes			+ X
2.4 Equipment is in place to cover waste disposal containers at the end of business day and during rain events		N/A			+ X	
2.5	2.5 Discharges from waste disposal containers are prevented from discharging to the storm drain system / receiving water		Yes			+ X
2.6	from wind and rai	material is securely protected n if not actively in use	N/A			+ X
2.7	Procedures are in and nonhazardou	n place for addressing hazardous as spills	Yes			+ X
2.8	Appropriate spill rassigned and train	response personnel are ned	Yes			+ X
2.9	available onsite	naterials for cleanup of spills is	Yes			+ X
2.10		e.g., concrete) are contained revent discharge or infiltration g soil	N/A			+ X
Ger	neral comments					
3	Good Houseke	eeping for Vehicle Storage a	ınd Maintena	nce		∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
3.1	fuel from leaking surface waters	place to prevent oil, grease, or into the ground, storm drains, or	Yes			+ X
3.2	All assistances as web into one finded maintained		+ X			
3.3		oment leaks are cleaned disposed of properly	Yes			+ X
Ger	neral comments					



Page 3 of 10

Higl	ect Name and Location nlands 8 Cobble Hill, San Mateo, CA					
4	Good Housekeeping for Air Deposition of	Site Materials	,	∑ Yes ☐ No)	Х
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	ation 1: Job site	1	<u>'</u>			Х
4.1	Good housekeeping measures are implemented onsite to control the air deposition of site materials and from site operations	Yes			+	Х
Ger	neral comments					
5	Non-Stormwater Management			∑ Yes ☐ No)	X
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
5.1	Non-Stormwater discharges are properly controlled	Yes			+	·
5.2	Vehicles are washed in a manner to prevent non- stormwater discharges to surface waters or drainage systems	N/A			+	X
5.3	Streets are cleaned in a manner to prevent unauthorized nonstormwater discharges to surface waters or drainage systems.	Yes			+	X
Ger	neral comments	•				
6	Erosion Controls			∑ Yes ☐ No)	X
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
6.1	Wind Erosion controls are effectively implemented	Yes			+	·X
6.2	Effective soil cover is provided for disturbed areas inactive (ie, not scheduled to be disturbed for 14 days) as well as finished slopes, open space, utility backfill, and completed lots	N/A			+	X
6.3	The use of plastic materials is limited in cases when more sustainable, environmentally friendly alternatives exists	Yes			+	X
Ger	neral comments					
7	Sediment Controls			∑ Yes ☐ No)	X
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
7.1	Perimeter controls are established and effective at controlling erosion and sediment discharges from the site	Yes			+	X
7.2	Entrances and exits are stabilized to control erosion and sediment discharges from the site	Yes			+	·x
7.3	Sediment basins are properly maintained	N/A			+	X
7.4	Linear sediment control along toe of slope, face of slope an at grade breaks (Risk Level 2 & 3 Only)	N/A			+	·
7.5	Limit construction activity to and from site to	N/A			+	X



BMP INSPECTION REPORT

of

10

4

Page

High	ect Name and Loca nlands					
218	8 Cobble Hill, San	Mateo, CA				
		its that employ effective controls tracking (Risk Level 2 & 3 Only)				
7.6	controls, runoff co controls at entran and protected from effectiveness (Ris	drain inlets and perimeter ontrol BMPs and pollutants ces and exits are maintained m activities the reduce their sk Level 2 & 3 Only)	Yes			+ X
7.7	Inspect all immed Level 2 & 3 Only)	liate access roads daily (Risk	Yes			+ X
Ger	neral comments					
8	Run-On and R	un-Off Controls				∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
8.1		e is effectively managed and m all disturbed areas.	Yes			+ X
Ger	neral comments					
Add	ditional space t	ACTION AND SWPPP M o describe inspection findi general location and the r	ings and corre	ective action	s if needed. Provide brief	Add Category





Location

Page 5 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL PHOTO	os	
Category			



Comments: Lot 9-10

Category

Location

Comments:

Remove Page





Page 6 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA		
	GENERAL PHOTOS	
Category		
Location		



Comments:	Lot 9-10
Category	
_ocation	

Comments: Remove Page





Page ______ of _____10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL	- PHOTOS	
Category			
Location			



	Wei (19/17/9/39 9/8 A)
Comments:	Lot 11
Category	
Location	

Comments:		

Remove Page





Page 8 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA		
	GENERAL PHOTOS	
Category		

Location



	A CONTRACTOR OF THE CONTRACTOR
Comments:	
Category	
Location	

Comments: Remove Page





Location

Page	9	of	10	

			<u> </u>
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL	. PHOTOS	
Category			
Location			
Comments:	Silt fence at Lot 11 needs reinstalling.	Wed,08/12/2020 9:39 AM	
Category			

Comments:

Remove Page

Add Page



BMP INSPECTION REPORT

Add Page

age 10 of 10

		Page _	10	of	10				
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA									
ACTION ITEM PHOTOS									
Category									
Location									
	Before Photo								
Comments:			7						
Comments.	After Photo								
Comments:] [Remov	ve Page				