

Page 1 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
GENERAL INFORMATION			
Date and Time of Inspection:	Date Report Written:		
Thu, 08/06/2020 09:32 AM	8/6/2020 2:40:01 PM		
Inspection Type:			

Weekly

SITE INFORMATION				
Construction Site Name:				
2188 Cobble Hill, San Mateo, CA				
Construction stage and completed activities:	Approximate area of site that is exposed:			
Vertical	80.00			
General Photo: 🛛 Yes 🗌 No	Action Photo: Yes No			
WEA	ATHER			
Estimate storm beginning:	Estimate storm duration:			
Estimate time since last storm:	Rain gauge reading and location:			
	0.00			
:Is a "Qualifying Event" predicted or did one occur (i.e., 0.5"	rain with 48-hrs or greater between events)?			
No				
Exemption Documentation (explanation required if inspection could not be conducted). Visual inspections are not required outside of business hours or during dangerous weather conditions such as flooding or electrical storms.				

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

CERTIFICATION STATEMENT AND SIGNATURES:

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

Neil Trenerry			Thu, 08/06/2020
Inspector's Name – Printed	Inspector's Signature	Inspector's Title	Date

Add Category

1 Good Housek	🗙 Yes 🗌 No 🛛 X				
Add	In Complaince	Action Required	Findings and Remedial actior	n documentation	
Location 1:	Job site				X



Page 2 of 12

	ect Name and Loca	ation						
	hlands 8 Cobble Lill See	Matao CA						
218	8 Cobble Hill, San	Maleo, CA						
1.1	Inventory of produced designed to be out	ucts (excluding materials utdoors)	Yes				+	+ X
1.2	Stockpiled constr use are covered a	uction materials not actively in and bermed	N/A				+	+ X
1.3		stored in watertight containers secondary containment, or in a sed storage shed	Yes				+	- X
1.4		erials are minimally exposed to	Yes				+	+ X
1.5	BMPs preventing	the off-site tracking of materials and properly effective	Yes				+	۲
Ger	neral comments		,					
2	Good Houseke	eping for Waste Manageme	ent			Yes 🗌 N	١o	X
	Add	Location	In	Action			_	_
	nuu	Location	Complaince	Required	Findings and Remedial actio	n documentatio	n	
	ation 4.		•	•			_	
LOC	cation 1:	Job site						X
2.1	from being dispos	and materials are prevented sed into the storm drain system	Yes				+	+ X
2.2	Portable toilets an discharges of was	re contained to prevent ste	Yes				+	+ X
2.3	Sanitation facilitie apparent for leaks	es are clean and with no s and spills	Yes				+	۲X
2.4		lace to cover waste disposal	N/A				+	۰X
	containers at the rain events	end of business day and during						
2.5		waste disposal containers are	Yes				٦.	
2.5	prevented from d	ischarging to the storm drain	res				+	١X
	system / receiving							_
2.6	from wind and rai	material is securely protected n if not actively in use	N/A					+ X
2.7	Procedures are ir and nonhazardou	n place for addressing hazardous is spills	Yes				+	+ X
2.8	assigned and trai		Yes				+	۲X
2.9	Equipment and m available onsite	aterials for cleanup of spills is	Yes				+	- X
2.10		e.g., concrete) are contained revent discharge or infiltration	N/A				+	۰X
	into the underlyin				•			_
Ger	neral comments							
3	Good Houseke	eping for Vehicle Storage a	and Maintena	nce		Yes 🗌 N	١o	X
	Add	Location	In	Action	Findings and Remedial actio	n documentatio	'n	
			Complaince	Required				_
Loc	ation 1:	Job site						X
3.1	Measures are in p	place to prevent oil, grease, or	Yes				-	+ X
0.1	fuel from leaking surface waters	into the ground, storm drains, or					Ľ]^
3.2		vehicles are fueled, maintained,	N/A				4	۰X
	and stored in a de BMPs	esignated area with appropriate			I		Ľ	
2 0		oment leaks are cleaned	Vee				T	
3.3		disposed of properly	Yes				+	+X
Ger	neral comments							



Page <u>3</u> of <u>12</u>

Higi	ect Name and Loc hlands 8 Cobble Hill, San							
4	Good Houseke	eeping for Air Deposition of	Site Materials	5		🛛 Yes 🗌 No	,	Х
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation		
Loc	cation 1:	Job site						х
4.1		ing measures are implemented he air deposition of site m site operations	Yes				+	X
Ger	neral comments							
5	Non-Stormwat	er Management				🛛 Yes 🗌 No	,	х
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation		
Loc	cation 1:	Job site						х
5.1	Non-Stormwater controlled	discharges are properly	Yes				+	Х
5.2		hed in a manner to prevent non- arges to surface waters or s	N/A				+	X
5.3	unauthorized nor	ed in a manner to prevent stormwater discharges to drainage systems.	Yes				+	X
Ger	neral comments							
6	Erosion Contr	ols				🛛 Yes 🗌 No	,	х
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation		
Loc	cation 1:	Job site						х
6.1	Wind Erosion cor	ntrols are effectively implemented	Yes				+	Х
6.2	inactive (ie, not s days) as well as f utility backfill, and		N/A				+	X
6.3		c materials is limited in cases inable, environmentally friendly s	Yes				+	X
Ger	neral comments							
7	Sediment Con	trols				🛛 Yes 🗌 No	,	Х
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation		
Loc	cation 1:	Job site						x
7.1	at controlling eros from the site	s are established and effective sion and sediment discharges	Yes				+	X
7.2		kits are stabilized to control ment discharges from the site	Yes				+	Х
7.3		are properly maintained	N/A				+	Х
7.4		control along toe of slope, face of breaks (Risk Level 2 & 3 Only)	N/A				+	Х
7.5		activity to and from site to	N/A				+	X



Page _____ of ____12

Hig	ect Name and Location hlands 8 Cobble Hill, San Mateo, CA			
	entrances and exits that employ effective controls to prevent offsite tracking (Risk Level 2 & 3 Only)			
7.6	Ensure all storm, drain inlets and perimeter controls, runoff control BMPs and pollutants controls at entrances and exits are maintained and protected from activities the reduce their effectiveness (Risk Level 2 & 3 Only)	Yes		+ X
7.7	Inspect all immediate access roads daily (Risk Level 2 & 3 Only)	Yes		+ X
Ge	neral comments			

III. CORRECTIVE ACTION AND SWPPP MODIFICATIONS DESCRIPTIONS:	Add Category
Additional space to describe inspection findings and corrective actions if needed. Provide brie	ef
explanation of the general location and the rationale for the additional or different BMPs	
1	Yes No X



Page 5 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category

Location



Comments: L

Category

Location



Page 6 of 12

Project Name and Location
Highlands
2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS Category Location Comments: Lot 9-10 Category Location



Page 7 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

	GENERAL	PHOTOS	
Category]
Location]
			1
Comments:	Lot 11		
Category]
Location]



Page 8 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Categor	y
---------	---

Location



Category

Location



Page 9 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS Category Location Comments: Category Location



Page 10 of 12

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category	y
----------	---

Location



Comments:

Talked about covering stockpile with plastic.

Category

Location



Page <u>11</u> of <u>12</u>

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	X					
GENERAL PHOTOS						
Category						
Location						
Comments:	Lot 11					
Category						
Location						

Comments:



Page <u>12</u> of <u>12</u>

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	Λ					
ACTION ITEM PHOTOS						
Category						
Location						

Before Photo

Comments:

After Photo