

Page 1 of 9

| Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA | | | | |
|---|-----------------------|--|--|--|
| GENERAL INFORMATION | | | | |
| Date and Time of Inspection: | Date Report Written: | | | |
| Wed, 10/28/2020 09:48 AM | 10/28/2020 4:11:39 PM | | | |
| | | | | |

Inspection Type:

Weekly

| SITE INFORMATION | | | |
|--|--|--|--|
| Construction Site Name: | | | |
| 2188 Cobble Hill, San Mateo, CA | | | |
| Construction stage and completed activities: | Approximate area of site that is exposed: | | |
| Vertical | 80.00 | | |
| General Photo: 🛛 Yes 🗌 No | Action Photo: Yes No | | |
| WEA | THER | | |
| Estimate storm beginning: | Estimate storm duration: | | |
| | | | |
| Estimate time since last storm: | Rain gauge reading and location: | | |
| | 0.00 | | |
| :Is a "Qualifying Event" predicted or did one occur (i.e., 0.5" i | rain with 48-hrs or greater between events)? | | |
| No | | | |
| Exemption Documentation (explanation required if inspection could not be conducted). Visual inspections are not required outside of business hours or during dangerous weather conditions such as flooding or electrical storms. | | | |
| | | | |

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

CERTIFICATION STATEMENT AND SIGNATURES:

Inspector – Certification: This section must be completed by the person who conducted the site inspection. *"I certify that this report is true, accurate, and complete, to the best of my knowledge and belief"*

| Neil Trenerry | N- | | Wed, 10/28/2020 |
|----------------------------|-----------------------|-------------------|-----------------|
| Inspector's Name – Printed | Inspector's Signature | Inspector's Title | Date |

Add Category

| 1 Good Housekeeping for Construction Material | | | | | 🗙 Yes 🗌 No 🛛 X |
|---|----------|------------------|--------------------|------------------------------|-----------------|
| Add Location | | In Complaince | Action Required | Findings and Remedial actior | n documentation |
| Location 1: | Job site | | | | X |



Page 2 of 9

| High | ect Name and Loca nlands 8 Cobble Hill, San | | | | | | | | |
|------|--|---|------------------|-----|---------------|-----------------------------|-----------------|---|---|
| 1.1 | Inventory of prod designed to be out | ucts (excluding materials utdoors) | Yes | | | | | + | X |
| 1.2 | Stockpiled constr use are covered a | uction materials not actively in and bermed | N/A | | | | | + | X |
| 1.3 | | stored in watertight containers secondary containment, or in a sed storage shed | Yes | | | | | + | X |
| 1.4 | Construction mat | erials are minimally exposed to | Yes | | | | | + | X |
| 1.5 | | the off-site tracking of materials and properly effective | Yes | | | | | + | X |
| Ger | neral comments | | 1 ' | | | | | | |
| 2 | Good Houseke | eeping for Waste Manageme | ent | | | | Yes 🗌 No |) | Х |
| | Add | Location | In Complaince | | tion uired | Findings and Remedial actio | n documentation | | |
| Loc | ation 1: | Job site | 1 | | | | | | Х |
| 2.1 | | r and materials are prevented sed into the storm drain system | Yes | | | | | + | X |
| 2.2 | | re contained to prevent | Yes | | | | | + | X |
| 2.3 | | es are clean and with no | Yes | | | | | + | X |
| 2.4 | Equipment is in p | lace to cover waste disposal end of business day and during | N/A | | | | | + | X |
| | rain events | , , | | | | | | _ | r |
| 2.5 | prevented from d system / receiving | waste disposal containers are ischarging to the storm drain a water | Yes | | | | | + | X |
| 2.6 | Stockpiled waste | material is securely protected in if not actively in use | N/A | | | | | + | X |
| 2.7 | Procedures are in and nonhazardou | n place for addressing hazardous is spills | Yes | | | | | + | X |
| 2.8 | Appropriate spill assigned and trai | response personnel are ned | Yes | | | | | + | X |
| 2.9 | Equipment and manales available onsite | naterials for cleanup of spills is | Yes | | | | | + | X |
| 2.10 | Washout areas (e appropriately to p into the underlyin | e.g., concrete) are contained prevent discharge or infiltration g soil | N/A | | | | | + | X |
| Ger | neral comments | | | | | | | | |
| 3 | Good Houseke | eeping for Vehicle Storage a | and Maintena | nce | | | Yes No | 2 | Х |
| | Add | Location | In Complaince | | tion uired | Findings and Remedial actio | n documentation | | |
| Loc | ation 1: | Job site | | | | | | | X |
| 3.1 | | place to prevent oil, grease, or into the ground, storm drains, or | Yes | | | | | + | X |
| 3.2 | | vehicles are fueled, maintained, esignated area with appropriate | N/A | | | | | + | X |
| 3.3 | | oment leaks are cleaned disposed of properly | Yes | | | | | + | X |
| Ger | neral comments | | • | | | | | | |



Page <u>3</u> of <u>9</u>

| Hig | ect Name and Loca hlands 38 Cobble Hill, San | | | | | |
|-----|---|--|------------------|--------------------|--|---|
| 4 | Good Houseke | eeping for Air Deposition of | Site Materials | 5 | Yes 🗌 No | x |
| | Add | Location | In Complaince | Action Required | Findings and Remedial action documentation | |
| Loc | cation 1: | Job site | | | | Х |
| 4.1 | | ing measures are implemented he air deposition of site m site operations | Yes | | + | X |
| Gei | neral comments | | | | | |
| 5 | Non-Stormwat | er Management | | | Yes 🗌 No | Х |
| | Add | Location | In Complaince | Action Required | Findings and Remedial action documentation | |
| Loc | cation 1: | Job site | | | | X |
| 5.1 | Non-Stormwater controlled | discharges are properly | Yes | | + | Х |
| 5.2 | | hed in a manner to prevent non- arges to surface waters or s | N/A | | + | Х |
| 5.3 | unauthorized non | ed in a manner to prevent istormwater discharges to drainage systems. | Yes | | + | X |
| Gei | neral comments | | | | | |
| 6 | Erosion Contro | ols | | | Yes 🗌 No | Х |
| | Add | Location | In Complaince | Action Required | Findings and Remedial action documentation | |
| Loc | cation 1: | Job site | | | | Х |
| 6.1 | Wind Erosion cor | ntrols are effectively implemented | Yes | | + | х |
| 6.2 | inactive (ie, not so days) as well as f utility backfill, and | | N/A | | + | X |
| 6.3 | | c materials is limited in cases inable, environmentally friendly s | Yes | | + | X |
| Gei | neral comments | | | | | |
| 7 | Sediment Con | trols | | | Yes 🗌 No | Х |
| | Add | Location | In Complaince | Action Required | Findings and Remedial action documentation | |
| Loc | cation 1: | Job site | | | | Х |
| 7.1 | | s are established and effective sion and sediment discharges | Yes | | + | X |
| 7.2 | | kits are stabilized to control ment discharges from the site | Yes | | + | X |
| 7.3 | | are properly maintained | N/A | | + | X |
| 7.4 | | control along toe of slope, face of breaks (Risk Level 2 & 3 Only) | N/A | | + | x |
| 7.5 | | activity to and from site to | N/A | | + | X |



Page <u>4</u> of <u>9</u>

| | ct Name and Loca lands | ation | | | |
|------|---------------------------|--|------------------|--------------------|--|
| | B Cobble Hill, San | Mateo, CA | | | |
| | | | | | |
| | | | | | |
| | | its that employ effective controls | | | |
| | • | tracking (Risk Level 2 & 3 Only) | | | |
| | | drain inlets and perimeter ontrol BMPs and pollutants | Yes | | + X |
| | | ces and exits are maintained | | | |
| | | m activities the reduce their | | | |
| | | sk Level 2 & 3 Only) | | | |
| | | iate access roads daily (Risk | Yes | | + X |
| | Level 2 & 3 Only) | | | | |
| Gen | eral comments | | | | |
| 8 | Run-On and R | un-Off Controls | | | Yes No X |
| | Add | Location | In Complaince | Action Required | Findings and Remedial action documentation |
| Loca | ation 1: | Job site | | | x |
| | | is effectively managed and mall disturbed areas. | Yes | | + X |
| Gene | eral comments | | | | |

| III. CORRECTIVE ACTION AND SWPPP MODIFICATIONS DESCRIPTIONS: | Add Category |
|--|--------------|
| Additional space to describe inspection findings and corrective actions if needed. Provide brief | |
| explanation of the general location and the rationale for the additional or different BMPs | |
| 1 | Yes No X |



Page <u>5</u> of <u>9</u>

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

| | GENERAL | . PHOTOS | |
|-----------|----------|----------|--|
| Category | | | |
| Location | | | |
| | | | |
| Comments: | Lot 9-10 | | |
| Category | | | |
| Location | | | |



Page 6 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

| Category | 1 |
|----------|---|
|----------|---|

Location



Location



Page 7 of 9

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS Category Location Comments: Lot 11 Category Location



Page <u>8</u> of <u>9</u>

| Project Name and Location |
|---------------------------------|
| Highlands |
| 2188 Cobble Hill, San Mateo, CA |

| | GENERAL | L PHOTOS | |
|-----------|---------|----------|---|
| Category | | |] |
| Location | | |] |
| | | | |
| Comments: | Lot 11 | |] |
| Category | | |] |
| Location | | |] |

Comments:



Page 9 of 9

| Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA | | | |
|---|--|--|--|
| ACTION ITEM PHOTOS | | | |
| Category | | | |
| Location | | | |

Before Photo

Comments:

After Photo

Comments: