

	rommen						Page _	1	of	7
Project Name and Loc Highlands 2188 Cobble Hill, San										
			GENERA	L INFORM	IATION	<u> </u>				
Date and Time of	Inspection:			Date	Report \	Written:				
Wed, 09/30/2020 0	9:37 AM			9/30/	2020 1:5	9:51 PM				
Inspection Type:				'						
Weekly										
			SITE II	NFORMA [*]	ΓΙΟΝ					
Construction Site	Name:									
2188 Cobble Hill, S	an Mateo, CA	١								
Construction stag	e and compl	eted activities	 S:	Appro	ximate	area of site tha	it is exposed	:		
Vertical				80.00						
General Photo: [>	Yes No	ı		Actio	Photo:	Yes 1	No			
			W	'EATHER						
Estimate storm beginning:			Estim	Estimate storm duration:						
Estimate time sind	ce last storm	:		Rain	gauge r	eading and loca	ation:			
				0.00	0.00					
:Is a "Qualifying E No Exemption Docu	mentation (explanation	required if in	spection	could r	not be conduc	ted). Visual	inspe		
required outside o	of business h	iours or during	g dangerous v	weather co	nditions	s such as flood	ing or electr	ical st	orms.	
						rson who cond e best of my kno				n.
CERTIFICATION	STATEMEN	IT AND SIGN	IATURES:							
Inspector – Certifi "I certify that this i								ction.		
Neil Trenerry N					We	ed, 09/	/30/20)20		
Inspector's Name – Printed Inspector's Signature		Inspe	ctor's Ti	tle	Date					
							<u> </u>		Ac	dd Category
1 Good Houseke	eeping for Co	onstruction Ma	aterial						Yes	□ No X
Add	Location		In Complaince	Action Required	F	indings and Re	medial actio	n doc	umen	tation
Location 1:	Job site									X





	Lilli	Tommental			Pa	age	2	of	7	_
High	ect Name and Loca nlands 8 Cobble Hill, San									
1.1	Inventory of producesigned to be out	ucts (excluding materials utdoors)	Yes							+ X
1.2		uction materials not actively in	N/A							+ X
1.3 All chemicals are stored in watertight containers with appropriate secondary containment, or in a completely enclosed storage shed		Yes							+ X	
1.4	1.4 Construction materials are minimally exposed to precipitation		Yes							+ X
1.5		the off-site tracking of materials and properly effective	Yes							+ X
Ger	neral comments									
2	Good Houseke	eeping for Waste Manageme	ent				×	'es	☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial	action	docur	ment	ation	
Loc	ation 1:	Job site	ı							X
2.1	from being dispos	and materials are prevented sed into the storm drain system	Yes							+ X
2.2	discharges of was		Yes							+ X
2.3	Sanitation facilitie apparent for leaks	es are clean and with no s and spills	Yes							+ X
2.4		lace to cover waste disposal end of business day and during	N/A							+ X
2.5	prevented from di system / receiving		Yes	ļ						+ X
2.6	from wind and rai	material is securely protected n if not actively in use	N/A							+ X
2.7	Procedures are in and nonhazardou	n place for addressing hazardous as spills	Yes							+ X
2.8	Appropriate spill rassigned and trai	response personnel are ned	Yes							+ X
2.9		naterials for cleanup of spills is	Yes							+ X
2.10		e.g., concrete) are contained revent discharge or infiltration g soil	N/A							+ X
Ger	neral comments									
3	Good Houseke	eeping for Vehicle Storage a	and Maintenar	nce			⊠ Y	'es	☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial	action	docur	ment	tation	
Loc	ation 1:	Job site	T							X
3.1	fuel from leaking surface waters	place to prevent oil, grease, or into the ground, storm drains, or	Yes							+ X
3.2 All equipment or vehicles are fueled, maintained, and stored in a designated area with appropriate BMPs		N/A							+ X	
3.3	Vehicle and equipole immediately and	oment leaks are cleaned disposed of properly	Yes							+ X
Cor	neral comments									



	LIIVI	Tommemea			Page	of	7	-
Higl	ect Name and Loca hlands 8 Cobble Hill, San							
4	Good Houseke	eping for Air Deposition o	of Site Material	s			☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n docume	ntation	
Loc	cation 1:	Job site	•					Х
4.1		ing measures are implemented he air deposition of site n site operations	Yes				4	+ X
Ger	neral comments							
5	Non-Stormwat	er Management					☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n docume	ntation	
Loc	cation 1:	Job site						X
5.1	Non-Stormwater controlled	discharges are properly	Yes				-	+ X
5.2		hed in a manner to prevent non arges to surface waters or	- N/A				-	+ X
5.3	Streets are cleane unauthorized non	ed in a manner to prevent stormwater discharges to drainage systems.	Yes				4	+ X
Ger	neral comments							
6	Erosion Contro	ols					☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n docume	ntation	
Loc	cation 1:	Job site	•					Х
6.1	Wind Erosion con	trols are effectively implemente	ed Yes				-	+ X
6.2	inactive (ie, not so	er is provided for disturbed area cheduled to be disturbed for 14 inished slopes, open space, I completed lots	N/A				Н	+ X
6.3	The use of plastic	materials is limited in cases inable, environmentally friendly	Yes				-	+ X
Ger	neral comments		•					
7	Sediment Con	trols					☐ No	X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n docume	ntation	
Loc	cation 1:	Job site						Х
7.1		s are established and effective sion and sediment discharges	No	Yes	Reinstalling Silt fence needs repairing/replacing	at Lot 11	4	+ X
7.2		its are stabilized to control ment discharges from the site	Yes				-	+ X
7.3		are properly maintained	N/A					+ X
7.4		control along toe of slope, face of breaks (Risk Level 2 & 3 Only)						+ X
7.5		activity to and from site to	N/A				-	+ X



Page 4 of 7



2188 Cobble Hill, San Mate	eo, CA				
		Yes			+ X
and protected from act effectiveness (Risk Le	and exits are maintained stivities the reduce their evel 2 & 3 Only) access roads daily (Risk	Yes			+ X
General comments					
8 Run-On and Run-C	Off Controls				
Add Loca	ation	In Complaince	Action Required	Findings and Remedial action	documentation
Location 1: Job	site				X
8.1 Run-on to the site is et directed away from all	ffectively managed and disturbed areas.	Yes			+ X
General comments					
Additional space to de	TION AND SWPPP Moscribe inspection finding	ngs and corre	ective action	s if needed. Provide brief	Add Category Yes No X





Page _____5 ___ of ____7

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL	_ PHOTOS	
Category			
Location]



	Wed, (19)30/2020 9:40 AM
Comments:	Lot 9-10
Category	
Location	

Comments:

Remove Page





Page	6	of	7
------	---	----	---

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA

GENERAL PHOTOS

Category
Location



	No. 1989 Control of the Control of t
Comments:	Lot 11
Category	
Location	

Comments:

Remove Page

Add Page



Comments:

BMP INSPECTION REPORT

LIIVII UIIIIII	a video de constante de constan	Page _	of _	7
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA				
	ACTION ITEM PHOTOS			
Category				
Location				
	Before Photo			
Comments:]	
	After Photo			

Remove Page

Add Page