

							Page	of	
Project Name and Loc Highlands 2188 Cobble Hill, San									
			GENERA	L INFORMA	ATION				
Date and Time of	Inspection:			Date R	eport Writte	n:			
Tue, 11/24/2020 0	9:58 AM			11/24/2	2020 3:48:07	PM			
Inspection Type:									
Weekly									
			SITE II	NFORMATI	ON				
Construction Site	Name:								
2188 Cobble Hill, S	San Mateo, CA	1							
Construction stag	e and compl	eted activities	:	Approx	imate area	of site that	is exposed:		
Vertical				80.00					
General Photo:	Yes No	1		Action	Photo:	Yes No)		
			W	'EATHER					
Estimate storm beginning:			Estima	Estimate storm duration:					
Estimate time sine	ce last storm	:		Rain ga	auge reading	g and locat	ion:		
				0.00					
:Is a "Qualifying E No Exemption Docu required outside o	mentation (explanation i	required if in	spection c	ould not be	conducte	e d). Visual i	nspections	are not
•		n: This section report is true,			•			•	n.
CERTIFICATION	STATEMEN	IT AND SIGN	ATURES:						
Inspector – Certifi "I certify that this								tion.	
Neil Tren	erry	2					Tue	e, 11/24/202	20
Inspector's Name	- Printed	Inspector's S	ignature	Inspect	or's Title		Date		
				l			1	Ad	d Category
1 Good Housek	eeping for Co	onstruction Ma	terial					∑ Yes	□ No >
Ado	l Location		In Complaince	Action Required	Finding	gs and Rem	edial action	document	ation
Location 1:	Job site								>



Page 2 of 11



High	ect Name and Loca nlands 8 Cobble Hill, San						
							_
1.1	Inventory of produ designed to be ou	ucts (excluding materials utdoors)	Yes		+	۲	(
1.2	Stockpiled construits use are covered a	uction materials not actively in and bermed	N/A		+	- X	′
1.3		stored in watertight containers secondary containment, or in a sed storage shed	Yes		<u>+</u>	×	(
1.4		erials are minimally exposed to	Yes		4	- X	(
1.5	BMPs preventing	the off-site tracking of materials and properly effective	Yes		+	٠ĺ×	(
Ger	neral comments		<u>'</u>	<u> </u>			=
2	Good Houseke	eping for Waste Manageme	ent		∑ Yes □ No	X	(
	Add	Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	ation 1:	Job site				X	(
2.1		and materials are prevented sed into the storm drain system	Yes		+	۲	(
2.2	Portable toilets ar discharges of was	e contained to prevent ste	Yes		+	- X	(
2.3	Sanitation facilitie apparent for leaks	s are clean and with no s and spills	Yes		+	- X	(
2.4	Equipment is in p	lace to cover waste disposal end of business day and during	N/A		4	×	(
2.5	•	waste disposal containers are scharging to the storm drain water	Yes		4	⊦ ×	(
2.6	Stockpiled waste	material is securely protected n if not actively in use	N/A		+	+ X	(
2.7	Procedures are in and nonhazardou	n place for addressing hazardous s spills	Yes		+	۲	(
2.8		esponse personnel are	Yes		+	- X	(
2.9	Equipment and mayailable onsite	aterials for cleanup of spills is	Yes		+	۲	(
2.10		e.g., concrete) are contained revent discharge or infiltration g soil	N/A		+	×	(
Ger	neral comments						
3	Good Houseke	eeping for Vehicle Storage a	ınd Maintenar	псе	∑ Yes ☐ No	X	′
	Add	Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	ation 1:	Job site				X	(
3.1		place to prevent oil, grease, or into the ground, storm drains, or	Yes		+	·Ι×	(
3.2		vehicles are fueled, maintained, esignated area with appropriate	N/A		+	⊦[×	(
3.3		oment leaks are cleaned disposed of properly	Yes		+	۲	(
Ger	neral comments						



Page _____ of ____11

Higl	ect Name and Loca hlands 8 Cobble Hill, San					
4	Good Houseke	eeping for Air Deposition of	Site Materials	3		∑ Yes ☐ No X
Add Location		In Complaince	Action Required	Findings and Remedial action	n documentation	
Loc	cation 1:	Job site				X
4.1		ing measures are implemented he air deposition of site m site operations	Yes			+ X
Ger	neral comments					
5	Non-Stormwat	er Management				∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	ı documentation
Loc	cation 1:	Job site				x
5.1	Non-Stormwater controlled	discharges are properly	Yes			+ X
5.2		hed in a manner to prevent non- arges to surface waters or	N/A			+ X
5.3	unauthorized non	ed in a manner to prevent stormwater discharges to drainage systems.	Yes			+ X
Ger	neral comments					
6	Erosion Contro	ols				∑ Yes ☐ No X
Add Location		In Complaince	Action Required	Findings and Remedial action	ı documentation	
Loc	cation 1:	Job site				X
6.1	Wind Erosion cor	ntrols are effectively implemented	Yes			+ X
6.2	inactive (ie, not se	er is provided for disturbed areas cheduled to be disturbed for 14 inished slopes, open space, I completed lots	N/A			+ X
6.3		materials is limited in cases inable, environmentally friendly s	Yes			+ X
Ger	neral comments					
7	Sediment Con	trols				∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	ı documentation
Loc	cation 1:	Job site				x
7.1		s are established and effective sion and sediment discharges	Yes			+ X
7.2 Entrances and exits are stabilized to control erosion and sediment discharges from the site		Yes	T		+ X	
7.3 Sediment basins are properly maintained		N/A			+ X	
7.4		control along toe of slope, face of breaks (Risk Level 2 & 3 Only)	N/A			+ X
7.5 Limit construction activity to and from site to		N/A	j		+ X	



BMP INSPECTION REPORT

LIIV	ironnicitai			Page _	4	of	11
Project Name and Loc Highlands 2188 Cobble Hill, Sar							
	xits that employ effective controls		<u> </u>				
7.6 Ensure all storm controls, runoff controls at entra and protected from	tracking (Risk Level 2 & 3 Only) drain inlets and perimeter control BMPs and pollutants nees and exits are maintained am activities the reduce their lisk Level 2 & 3 Only)	Yes					+ X
7.7 Inspect all imme Level 2 & 3 Only	diate access roads daily (Risk	Yes					+ X
General comments							
8 Run-On and F	Run-Off Controls				Y	es [No X
Add	Location	In Complaince	Action Required	Findings and Remedial action	on docu	menta	ation
Location 1:	Job site						X
	re is effectively managed and om all disturbed areas.	Yes					+ X
General comments							
Additional space	ACTION AND SWPPP M to describe inspection findic general location and the r	ngs and corre	ective action	ns if needed. Provide brief		Add C	Category
4						, _	





Page 5 of 11

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA					
GENERAL PHOTOS					

Location

Category



Comments:	Lot 11
Category	
Location	

Comments:





Page 6 of 11

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	
GE	NERAL PHOTOS

Category

Location



Lot 9-10

Comments:





Page 7 of 11

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL	L PHOTOS	
Category			
Location			
Comments:	Lot 11		
Category			
Location			

Comments:





Location

			Page _	0	_ of	11
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA						
	GENERAL	PHOTOS				
Category]		
Location]		
Comments: Lot 11						
]		
Category						

Comments:		
-----------	--	--





Page 9 of 11

			oi 11
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL	- PHOTOS	
Category [
Location			
Comments:	Lot 9-10		
L			
Category			
Location			

Comments:





Page 10 of 11

		-									
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA											
GENERAL PHOTOS											
Category											
Location											
Comments:	Lot 9-10										
Category]								
Location											

Comments:

Remove Page

Add Page



BMP INSPECTION REPORT

Page of Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA **ACTION ITEM PHOTOS** Category Location Before Photo Comments: After Photo

Comments: Remove Page

Add Page

Forecast For Lat/Lon: 37.5110/-122.3420 (Elev. 440 ft) 2 Miles W Belmont CA

Forecast Created at: 4am PST Nov 24, 2020

Custom Weather Forecast Table

	Tue Nov 24			Wed Nov 25				Thu Nov 26				Fri Nov 27				Sat Nov 28				Sun Nov 29				Mon Nov 30				
Weather																												
Daily-					High 61				High 62				High 63				High 63				High 64				High			
Temp	Low-				Low 47				Low 43				Low 42				Low 42				Low 42				Low 44			
Chance of Precip	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	5%	0%	0%
Precip	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00'	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00'	0.00"	0.00'	0.00"				
12-hr Snow Total	0" 0"			0"		0"		0" 0"		0"		0"		0"														
6-Hour	4am	10am	4pm	10pm	4am	10am	4pm	10pm	4am	10am	4pm	10pm	4am	10am	4pm	10pm	4am	10am	4pm	10pm	4am	10an	4pm	10pm	4am	10am	4pm	10pm
Temp	47	58	58	48	49	56	58	49	46	55	60	50	46	55	61	49	44	54	61	48	44	55	62	50	46	56	61	0
Cloudiness	32%	25%	16%	80%	76%	18%	9%	10%	17%	11%	7%	9%	15%	10%	6%	13%	27%	17%	19%	33%	47%	41%	39%	50%	72%	66%	54%	0%
Dewpoint	42	46	48	44	46	45	44	40	38	40	39	31	29	36	40	35	33	38	40	33	31	39	42	37	37	45	47	0
Relative Humidity	81%	65%	67%	84%	89%	66%	60%	70%	72%	57%	45%	47%	52%	49%	45%	57%	63%	55%	46%	57%	62%	54%	48%	61%	70%	67%	61%	0%
Wind	SW 1	E 5	SW 9	W 9	SW 5	NW 14	NW 15	NW 5	NW 5	N 9	N 6	N 6	NE 5	NE 7	N 3	NE 2	E 3		N 3	NE 2	E 3	NE 6	N 5	N 2	NE 2	NE 5	NW 5	NE 3
Snow Level (ft)	6536	6929	6850	6982	5748	3386	4121	4147	3648	3517	3885	4121	3990	4645	4829	5144	5171	5564	5669	5827	5696	5827	5748	5801	5696	5591	6273	0