

	rommen						Page	1	_ of _	10
Project Name and Loca Highlands 2188 Cobble Hill, San										
			GENERA	L INFORM	ATION					
Date and Time of	Inspection:			Date F	Report Writt	en:				
Mon, 12/28/2020 1	1:46 AM			12/28/	2020 2:28:4	7 PM				
Inspection Type:				<b>'</b>						
Weekly										
			SITE II	NFORMAT	ION					
Construction Site	Name:									
2188 Cobble Hill, S	an Mateo, CA	١								
Construction stage	e and compl	eted activities	S:	Appro	kimate area	of site that	is exposed	:		
Vertical				70						
General Photo: D	Yes No	ı		Action	Photo:	Yes No	)			
			W	'EATHER						
Estimate storm be	eginning:			Estima	Estimate storm duration:					
Wed, 12/16/2020 0	)4:00 PM			48.00	48.00					
Estimate time sind	ce last storm	:		Rain g	auge readi	ng and locat	ion:			
				0.00						
:ls a "Qualifying E	vent" predic	ted or did one	e occur (i.e., 0	.5" rain wit	n 48-hrs or	greater betw	een event	s)?		
Yes  Exemption Docu required outside o	of business h	ours or durin	g dangerous v	weather co	nditions suc	ch as floodin	g or electri	cal st	orms	
			on must be col e, <i>accurate, an</i>							on.
CERTIFICATION	STATEMEN	IT AND SIGN	IATURES:							
Inspector – Certifi "I certify that this i								ction.		
Neil Trenerry N			Mon, 12/28/2020			)20				
Inspector's Name – Printed Inspector's Signature			Inspec	tor's Title		Date				
									Ac	ld Category
1 Good Houseke	eeping for Co	onstruction M	aterial						Yes	☐ No X
Add	Location		In Complaince	Action Required	Findi	ngs and Rem	edial action	n doc	umen	tation
Location 1:	Job site									x



10

2 of

Page



High	ect Name and Loca nlands 8 Cobble Hill, San					
1.1	Inventory of produ designed to be ou	ucts (excluding materials	Yes			+ X
1.2		uction materials not actively in	N/A			+ X
1.3		stored in watertight containers secondary containment, or in a sed storage shed	Yes			+ X
1.4	Construction mate precipitation	erials are minimally exposed to	Yes			+ X
1.5		the off-site tracking of materials and properly effective	Yes			+ X
Ger	neral comments					
2	Good Houseke	eeping for Waste Manageme	ent			∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
2.1		and materials are prevented sed into the storm drain system	Yes			+ X
2.2	Portable toilets ar discharges of was	re contained to prevent ste	Yes			+ X
2.3	apparent for leaks		Yes			+ X
2.4	Equipment is in p containers at the rain events	lace to cover waste disposal end of business day and during	N/A			+ X
2.5	Discharges from v prevented from di system / receiving	waste disposal containers are ischarging to the storm drain gwater	Yes			+ X
2.6	from wind and rai	material is securely protected n if not actively in use	N/A			+ X
2.7	Procedures are in and nonhazardou	n place for addressing hazardous as spills	Yes			+ X
2.8	Appropriate spill rassigned and train	response personnel are ned	Yes			+ X
2.9	available onsite	naterials for cleanup of spills is	Yes			+ X
2.10		e.g., concrete) are contained revent discharge or infiltration g soil	N/A			+ X
Ger	neral comments					
3	Good Houseke	eeping for Vehicle Storage a	ınd Maintena	nce		∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
3.1	fuel from leaking surface waters	place to prevent oil, grease, or into the ground, storm drains, or	Yes			+ X
3.2	and stored in a de BMPs	vehicles are fueled, maintained, esignated area with appropriate	N/A			+ X
3.3		oment leaks are cleaned disposed of properly	Yes			+ X
Ger	neral comments					



Page 3 of 10

Higl	ect Name and Location nlands 8 Cobble Hill, San Mateo, CA					
4	Good Housekeeping for Air Deposition of	Site Materials	,	∑ Yes ☐ No	)	Х
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	ation 1: Job site	1	<u>'</u>			Х
4.1	Good housekeeping measures are implemented onsite to control the air deposition of site materials and from site operations	Yes			+	Х
Ger	neral comments					
5	Non-Stormwater Management			∑ Yes ☐ No	)	Х
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
5.1	Non-Stormwater discharges are properly controlled	Yes			+	·
5.2	Vehicles are washed in a manner to prevent non- stormwater discharges to surface waters or drainage systems	N/A			+	X
5.3	Streets are cleaned in a manner to prevent unauthorized nonstormwater discharges to surface waters or drainage systems.	Yes			+	X
Ger	neral comments	•				
6	Erosion Controls			∑ Yes ☐ No	)	X
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
6.1	Wind Erosion controls are effectively implemented	Yes			+	·X
6.2	Effective soil cover is provided for disturbed areas inactive (ie, not scheduled to be disturbed for 14 days) as well as finished slopes, open space, utility backfill, and completed lots	N/A			+	X
6.3	The use of plastic materials is limited in cases when more sustainable, environmentally friendly alternatives exists	Yes			+	X
Ger	neral comments					
7	Sediment Controls			∑ Yes ☐ No	)	X
	Add Location	In Complaince	Action Required	Findings and Remedial action documentation		
Loc	Job site					Х
7.1	Perimeter controls are established and effective at controlling erosion and sediment discharges from the site	Yes			+	X
7.2	Entrances and exits are stabilized to control erosion and sediment discharges from the site	Yes			+	·x
7.3	Sediment basins are properly maintained	N/A			+	X
7.4	Linear sediment control along toe of slope, face of slope an at grade breaks (Risk Level 2 & 3 Only)	N/A			+	·
7.5	Limit construction activity to and from site to	N/A			+	X



## **BMP INSPECTION REPORT**

of

10

4

Page

High	ect Name and Loca nlands					
218	8 Cobble Hill, San	Mateo, CA				
		its that employ effective controls tracking (Risk Level 2 & 3 Only)				
7.6	controls, runoff co controls at entran and protected from effectiveness (Ris	drain inlets and perimeter ontrol BMPs and pollutants ces and exits are maintained m activities the reduce their sk Level 2 & 3 Only)	Yes			+ X
7.7	Inspect all immed Level 2 & 3 Only)	liate access roads daily (Risk	Yes			+ X
Ger	neral comments					
8	Run-On and R	un-Off Controls				∑ Yes ☐ No X
	Add	Location	In Complaince	Action Required	Findings and Remedial action	n documentation
Loc	ation 1:	Job site				X
8.1		e is effectively managed and m all disturbed areas.	Yes			+ X
Ger	neral comments					
Add	ditional space t	ACTION AND SWPPP M o describe inspection findi general location and the r	ings and corre	ective action	s if needed. Provide brief	Add Category





Page 5 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA		
	GENERAL PHOTOS	
Category		

Location



Con 9 Shido 25 translaw
Lot 11

Comments:

Remove Page





Location

Page 6 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA			
	GENERAL PH	отоѕ	
Category			



	Mon,12/28/2020 11:50 AM
Comments:	Lot 9-10
Category	
Location	

Comments:

Remove Page





Page 7 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	A		
	GENERAL	_ PHOTOS	
Category			
Location			
		MOS, 12/30/2/020 11/47/AN	
Comments:	Lot 11		
Category			
Location			

Comments: Remove Page





Page 8 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA				
GENERAL PHOTOS				
Category				
Location				



Comments:	Lot 9-10
Category	
Location	

Comments:		Remove Page





Page 9 of 10

Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA	Α.		
	GENERA	L PHOTOS	
Category			
Location			
		Mon, 12/28/2020 11-53 AM	
Comments:	Lot 9-10		
Category			
Location			

Comments:

Remove Page

Add Page



## **BMP INSPECTION REPORT**

Add Page

age 10 of 10

		Page _	10	of _	10		
Project Name and Location Highlands 2188 Cobble Hill, San Mateo, CA							
ACTION ITEM PHOTOS							
Category							
Location							
	Before Photo						
Comments:							
	After Photo						
			_				
Comments:				Remo	ve Page		