FAILURE TO CORRECT VIOLATION(S) within 10 business days (or as specified in this notice) may result in PENALTIES described on page 2!

	MATED COUNTYWIDE Water Pollution	CONSTRUCT	ION SITE INSPECTION REPORT	
Pre	Inspection Date: 10/14/2020	1a. Current weather	conditions:Sunny, clear, 70F	
2.	Name of Project: Highland Estates		2a. Project No./Permit No. BLD2016-00160	
3	3. Project Address: Highland Estates, Lots 9, 10, and 11 San Mateo, Ca, 94402			
	4. Inspection Type: Routine Follow-up Other			
	Permit Type: Building Permit	Grading Permit	Site Development CIP Project	
6.	Project disturb ≥ 1 acre?: Y (Y/N - If Yes)		g wet season.) NOI Required: Y (Y/N) SWPPP dated 10 / 30 / 2019	
	Project covered under statewide Construct	tion General Permit?_		
	 7. High Priority Site (significant threat to water quality)? Y 7. High Priority Site (significant threat to water quality)? Y 7. High Project?Y 8. Project Type: I Residential I Commercial/Industrial I Institutional I Landscaping 9. Street Improvement I Other: 			
9.	Erosion Control Measures:	<u>(A / NM / P / NA)*</u>	Location on site/Comments	
	Jute Netting/Fiber Blankets	NA		
	Mulch	NA		
	Hydroseed/Soil binder/Compost blanket	NA		
	Mark Areas to be Preserved	NM	Silt fence and orange snow fence were in place around the project. Silt fence needs repair on east side of Lot 11	
	 Tree Protection Fencing 	A		
	Riparian Area Barrier	NM	Orange snow fencing is in place to delineate the tree protection zones. Chain link fence is in place to protect the riparian area on Lot 11, however a portion of the fence was opened up and requires repair.	
10				
10.	Stabilized construction entrance			
	-	A	Stabilized construction entrance is in place at Lots 9, 10 and 11	
	Street Sweeping	A	No trackout was observed, daily street sweeping is being conducted as needed.	
	Dust Control	A	Twice a day watering is required by AQ-1. NextGen has been logging the watering times in a logbook onsite.	
	Wattles / Fiber Rolls / Compost Socks	A	Fiber rolls were in place along the silt fence of Lot 11.	
	Silt Fences / Compost Berms	NM	Silt fence is installed around the perimeter of the site, however silt fence needs repair on E side of Lot 11	
	Sedimentation Basin	NA		
	Check Dams	NA		
	✓ Inlet Filters (Gravel bags)	NM	Drain inlet protection is required at the entrance to Lots 9/10. Inlet protection was discussed with NextGen.	
	Earth Dikes / Drainage Swales	NA		
11.	Run-on and Runoff Control			
	 Earth Dikes / Drainage Swales 	А	Permanent stormwater system has been installed on Lot 10.	
	Sampling is conducted, if required	NA		
12.	Active Treatment System (if any)	NA		
13.	Good Site Management			
	Soil Stockpiles	NA		
	✓ Waste Systems Management	А	Port-o-john onsite was in good working order and is within secondary containment.	
	ConstructionMaterials (wood,cement,)	NM	Debris and pallets of construction materials were present onsite on Lots 9, 10, and 11. Staged materials need to be removed from sidewalk and contained within Lot 9/10.	
	Hazardous Materials (paint, solvents)	NA		
	 Petroleum Products (oil, fuel) 	A	Generators and gas cans were within secondary containment.	
	Vehicle Servicing	А	Onsite equipment was in good working order.	
14.	Non-Stormwater Management			
	Concrete/Stucco washout area	NA		
	Architectural copper rinsewater	NA		
	✓ Other:	NM	Wind break on N side of Lot 11 requires repair.	
* A=	- Adequate, NM=needs maintenance, P=Problem(s)	, NA=Not Applicable		
15.	Is there an actual illicit discharge or evide	nce of illicit discharge	to storm drain/discharge point? Ves No	
16. Comments: Final C.6 Inspection				
17.	17. Enforcement/Follow-Up Date problem first identified: 10/9/2020 Next follow-up inspection date: 10/21/2020			
			et protection, construction material maintenance, and windbreak repair required. All issues have been discussed with NextGen.	
1	Enforcement: Done/In compliance Derbal Warning Dotice of Violation Dotice to Comply Dote Stop Work Dote Administrative Fine			
18	18. Resolution: Problem Fixed Need More Time (include rationale in comments) Escalate Enforcement Date resolved: / /			
10.	Was there rain with runoff after problem identified and before resolution? Ves No			
1				
L	Comments:			
19.	Inspector's Signature: prsietHIMBen		Date: 10/14/2020	
	Inspector's Name (Print): Jessica Henderson	-McBean	Phone Number: 8057128794 no responsible	
20	Name of Site Contact Person (Print) Robe	rt Pellearine	person present.	
20.				
	Site Contact Signature	Job Ti	itle: <u>Superintendent</u> Date: Left report copy at site.	

NOTES AND DEFINITIONS OF TERMS USED IN THE CONSTRUCTION SITE INSPECTION REPORT

NOTES:

PENALTIES. Agency staff are required to verify correction of any stormwater violations within 10 business days or before the next rainfall with runoff. If a violation is not corrected within this time frame, enforcement will escalate per the Enforcement Response Plan. This may result in the jurisdiction taking one or all of the following actions: 1) Issuance of a Stop Work Notice (such that inspections on all permits will be stopped until all violation(s) have been corrected); 2) Application of fines/re-inspection fees of \$_____ per day; 3) and/or Referral of the violation(s) to the Regional Water Quality Control Board. Erosion control measures, or other best management practices, in addition to those shown on the plans may be required by agency staff to ensure effective stormwater management.

Stormwater Inspection Requirement - Agency staff are required to inspect the following categories of sites at least once per month during the rainy season: sites that disturb 1 acre of land or more, Hillside Projects and High Priority Sites (see definitions below).

Construction General Permit Compliance - Projects that disturb 1 acre or more of land are required to obtain coverage under the statewide Construction General Permit (see

www.swrcb.ca.gov/water_issues/programs/stormwater/constpermits.shtml for information and to download the permit). To obtain coverage under the Construction General Permit, file a Notice of Intent using the SMARTS database, at https://smarts.waterboards.ca.gov/smarts/faces/SwSmartsLogin.xhtml.

Requirement to Verify Construction General Permit Coverage - Agency staff must verify that projects disturbing one acre or more of land have obtained coverage under the statewide Construction General Permit.

Where to Find Information on Construction BMPs - Detailed information on construction best management practices (BMPs) is available at the California Stormwater Quality Association's online Construction BMP Portal, at www.casqa.org/resources/bmp-handbooks. A subscription fee is required to access the portal. For information on access to the portal, inspectors should contact their agency's representative to the Countywide Program's New Development Subcommittee.

DEFINITIONS:

Active Treatment System - Active Treatment Systems (ATS) reduce turbidity of construction site runoff by collecting runoff in a tank and introducing chemicals through direct dosing or an electrical current to enhance flocculation, coagulation, and settling of the suspended sediment. The increased flocculation aids in sedimentation and ability to remove fine suspended sediments, thus reducing stormwater runoff turbidity and improving water quality.

Check Dam - a small barrier constructed of rock, gravel bags, sandbags, fiber rolls, or other proprietary products, placed across a constructed swale or drainage ditch. Check dams reduce the effective slope of the channel, thereby reducing scour and channel erosion by reducing flow velocity and increasing residence time within the channel, allowing sediment to settle.

High Priority Site - A site that has a steep slope or is adjacent to a creek or other water body, or a site that the agency or the Regional Water Quality Control Board (Water Board) has determined to have significant threat to water quality based on site-specific evaluation of the following additional factors: soil erosion potential or soil type, project size and type, sensitivity of receiving water bodies, proximity to receiving water bodies, non-stormwater discharge, or any other relevant factors as determined by the local agency or Water Board.

Illicit Discharge - Any discharge to a municipal storm drain system that is prohibited under local, state, or federal law, including all non-stormwater discharges not composed entirely of stormwater and discharges prohibited under the Municipal Regional Stormwater Permit (MRP).

Hillside Project - As defined in the MRP, those projects on sites disturbing 5,000 square feet or more of land area and with slopes greater than or equal to 15% (or based on the Permittee's map of hillside development areas or criteria.)