FAILURE TO CORRECT VIOLATION(S) within 10 business days (or as specified in this notice) may result in PENALTIES described on page 2! AN MATEO COUNTYWIDE Water Pollution Prevention Program CONSTRUCTION SITE INSPECTION REPORT 1. Inspection Date: 08/19/2021 Sunny, 65F 1a. Current weather conditions: __ 2. Name of Project: Highland Estates 2a. Project No./Permit No. BLD2016-00160 3. Project Address: Highland Estates, Lots 9, 10, and 11 San Mateo, Ca, 94402 Routine ☐ Follow-up ☐ Other 4. Inspection Type: Grading Permit ☐ Site Development 5. Permit Type: Building Permit □ CIP Project 6. Project disturb ≥ 1 acre?: <u>v</u> (Y/N - If Yes, inspect monthly during wet season.) NOI Required: Y (Y/N) SWPPP dated 10 / 30 / Project covered under statewide Construction General Permit?____ SWPPP on site? N (Y/N) 7.a Hillside Project? High Priority Site (significant threat to water quality)? Y (Y/N - If Yes, inspect monthly during wet season.) 8. Project Type: Residential ☐ Commercial/Industrial ■ Institutional Landscaping ■ Utility (water, sewer, PG&E) □ Grading Demolition □ Street Improvement Other: Inspection Finding (A / NM / P / NA)* Location on site/Comments 9. Erosion Control Measures: Jute Netting/Fiber Blankets ☐ Mulch NA Hvdroseed/Soil binder/Compost blanket NA NM Mark Areas to be Preserved Silt fence is in place around all project sites. Orange snow fence is in place to protect trees onsite. Silt fence on Lot 11 requires repair Tree Protection Fencing Α ✓ Riparian Area Barrier Α Chain link fence is in place to protect the riparian area on Lot 11. 10. Sediment Control Measures ✓ Stabilized construction entrance Stabilized construction entrance is in place at Lots 9/10 and 11 $\overline{\mathbf{V}}$ Street Sweeping Α No trackout was observed. NextGen will continue to sweep the street and use wheel wash as required by AQ-1 **√** Dust Control Α Twice daily watering will be conducted as needed per AQ-1 during any ground disturbing activites Wattles / Fiber Rolls / Compost Socks Α Fiber rolls are in place around project sites NM $\overline{}$ Silt Fences / Compost Berms Silt fence is in place around project sites, however fence on Lot 11 has fallen down on the South side and requires repair Sedimentation Basin NA Check Dams NA ✓ Inlet Filters (Gravel bags) Α Drain inlet protection is in place at Lot 9/10. Earth Dikes / Drainage Swales NA 11. Run-on and Runoff Control ▼ Earth Dikes / Drainage Swales Permanent stormwater system has been installed on Lot 10 Sampling is conducted, if required NA 12. Active Treatment System (if any) NA 13. Good Site Management Soil Stockpiles NA Waste Systems Management Port-o-johns onsite was in good working order and are within secondary containment. \square ConstructionMaterials (wood,cement,...) Construction materials are onsite, debris containers are available for trash, and construction materials are within the project area Hazardous Materials (paint, solvents) Α Stucco clean up has occurred, and plastic removed. Petroleum Products (oil, fuel) Α Gas cans and generators were observed within secondary containment ✓ Vehicle Servicing Secondary containment is present beneath parked equipment, and oil drips have been repaired. Non-Stormwater Management Plastic capturing stucco was cleaned up - continued clean up of stucco will occur during final grading. ✓ Concrete/Stucco washout area Architectural copper rinsewater NA Other: Wind break on N side of Lot 11 is in place.

A=	=Ade	quate,	NIVI=needs	mair	itena	ance,	P=Problem(s),	IVA=IVOT	App	licat	ole

15. Is there an actual illicit discharge or evidence of illicit discharge to storm drain/discharge point?	Yes 🔳 No
16. Comments:	Final C.6 Inspection

17.	Enforcement/Follow-up Date problem first identified: 1920/21 Next follow-up inspection date: 920/2021							
	Comments: See above for required site maintenance. All issues have been discussed with NexGen.							
	Enforcement:							
18.	Resolution: Problem Fixed Need More Time (include rationale in comments) Escalate Enforcement Date resolved: //							
	Was there rain with runoff after problem identified and before resolution? \square Yes \square No \square Items corrected during inspection (see comments)							
	Comments:							
19.	Inspector's Signature:							

19. Inspector's Signature:	Date	e: 08/19/2021		No one on site or
Inspector's Name (Print): Jessie Henderson-McBean	Phone Number: 80)57128794		no responsible person present.
20. Name of Site Contact Person (Print) Bob Pellegrine	Pho	one No. <u>6504452214</u>	_	
Site Contact Signature	Job Title · NexGen Foreman	Date [.]		Left report copy at

site

NOTES AND DEFINITIONS OF TERMS USED IN THE CONSTRUCTION SITE INSPECTION REPORT

NOTES:

PENALTIES. Agency staff are required to verify correction of any stormwater violations within 10 business days or before the next rainfall with runoff. If a violation is not corrected within this time frame, enforcement will escalate per the Enforcement Response Plan. This may result in the jurisdiction taking one or all of the following actions: 1) Issuance of a Stop Work Notice (such that inspections on all permits will be stopped until all violation(s) have been corrected); 2) Application of fines/re-inspection fees of \$______ per day; 3) and/or Referral of the violation(s) to the Regional Water Quality Control Board. Erosion control measures, or other best management practices, in addition to those shown on the plans may be required by agency staff to ensure effective stormwater management.

Stormwater Inspection Requirement - Agency staff are required to inspect the following categories of sites at least once per month during the rainy season: sites that disturb 1 acre of land or more, Hillside Projects and High Priority Sites (see definitions below).

Construction General Permit Compliance - Projects that disturb 1 acre or more of land are required to obtain coverage under the statewide Construction General Permit (see www.swrcb.ca.gov/water_issues/programs/stormwater/constpermits.shtml for information and to download the permit). To obtain coverage under the Construction General Permit, file a Notice of Intent using the SMARTS

database, at https://smarts.waterboards.ca.gov/smarts/faces/SwSmartsLogin.xhtml.

Requirement to Verify Construction General Permit Coverage - Agency staff must verify that projects disturbing one acre or more of land have obtained coverage under the statewide Construction General Permit.

Where to Find Information on Construction BMPs - Detailed information on construction best management practices (BMPs) is available at the California Stormwater Quality Association's online Construction BMP Portal, at www.casqa.org/resources/bmp-handbooks. A subscription fee is required to access the portal. For information on access to the portal, inspectors should contact their agency's representative to the Countywide Program's New Development Subcommittee.

DEFINITIONS:

Active Treatment System - Active Treatment Systems (ATS) reduce turbidity of construction site runoff by collecting runoff in a tank and introducing chemicals through direct dosing or an electrical current to enhance flocculation, coagulation, and settling of the suspended sediment. The increased flocculation aids in sedimentation and ability to remove fine suspended sediments, thus reducing stormwater runoff turbidity and improving water quality.

Check Dam - a small barrier constructed of rock, gravel bags, sandbags, fiber rolls, or other proprietary products, placed across a constructed swale or drainage ditch. Check dams reduce the effective slope of the channel, thereby reducing scour and channel erosion by reducing flow velocity and increasing residence time within the channel, allowing sediment to settle.

High Priority Site - A site that has a steep slope or is adjacent to a creek or other water body, or a site that the agency or the Regional Water Quality Control Board (Water Board) has determined to have significant threat to water quality based on site-specific evaluation of the following additional factors: soil erosion potential or soil type, project size and type, sensitivity of receiving water bodies, proximity to receiving water bodies, non-stormwater discharge, or any other relevant factors as determined by the local agency or Water Board.

Illicit Discharge - Any discharge to a municipal storm drain system that is prohibited under local, state, or federal law, including all non-stormwater discharges not composed entirely of stormwater and discharges prohibited under the Municipal Regional Stormwater Permit (MRP).

Hillside Project - As defined in the MRP, those projects on sites disturbing 5,000 square feet or more of land area and with slopes greater than or equal to 15% (or based on the Permittee's map of hillside development areas or criteria.)